

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: Fuel Spill DATE OCCURRED 01-05-92 DATE REPORTED _____
 Unleaded Auto Gas TIME OCCURRED 2001 TIME REPORTED _____

LOCATION(S) OF OCCURRENCE:
 Northend Fuel Farm

REPORTED BY: Jason, Galvin's PHONE NO(S): _____

SUMMARY:

Galvin's reported a fuel spill at the fuel farm. I responded and contacted Bruce Renner, Galvin lineman, about the spill. Renner stated he was filling the under-door saddle tank for the Chev #023 Avgas truck. He had engaged the stock manual lever which holds the nozzle valve in the open position. He went around the truck to do something else. The lever device on the nozzle did not release when the tank was full, spilling approx. 5 gallons onto the pavement before Renner was able to shut it off. The spill was washed down with Cejor and 100 gallons of water from FD#2. The mogas spilled was to power the engine of the Chev fuel truck.

cc: Ole Olsen

LEB	OLD	CO	JW
JEB	JE	LOR	FILED
BLC	TKL	BOS	BY
SHD	PEM	JRV	

OFFICERS: P.E. Mathison

ACTION: